



KERALA STATE ELECTRICITY BOARD LIMITED

(Incorporated under the Companies Act, 1956)

Reg. Office: Vidyuthi Bhavanam, Pattom, Thiruvananthapuram – 695 004

CIN:U40100KL2011SGC027424 Website: www.kseb.in

Phone: +91 471 2514685, 2514331, Fax: 0471 2447228 E-mail: ddkseb@kseb.in



Abstract

Construction of Inspection Bungalow at Burnassery, Kannur under Electrical Circle, Kannur –
Revised Administrative Sanction – Sanctioned – Orders issued

CORPORATE OFFICE (SBU-D)

B.O.(FTD) No.513/2020 (D(D&IT)/D/AEC/Bldg/5285/2018) Dated, Thiruvananthapuram, 14/08/2020

- Read: 1. B.O.(FTD) No. 858/2019 (D(D&IT)/D/AEC/Bldg/ 5285/2018) dated 22/11/2019
2. Letter No. CE/TS-C/IB-Kannur/2018-19/01 dated 03/04/2020 of the Chief Engineer (Distribution North Malabar), Kannur
3. Note No. D(D&IT)/D/AEC/Bldg/5285/2018 dated 11/08/2020 of the Director (Distribution, IT & HRM) to the Full Time Directors (Agenda Item No. 40/8/20)

ORDER

As per B.O. read as 1st above Administrative Sanction was accorded for an amount of ₹133.70 lakh for the construction of Inspection Bungalow at Burnassery, Kannur as the first phase in the land owned by KSEB Ltd at Burnassery, Kannur.

The Chief Engineer (Distribution North Malabar), Kannur as per letter read as 2nd above requested revised Administrative Sanction for an amount of ₹185 lakh for the above building based on the detailed estimate prepared from the office of the Project Manager, Pazhassi Sagar SHEP, Chavasseri based on sub soil investigation report and structural design of the building. It is reported that the increase in amount is mainly due to variation in DSR and the foundation provided for future expansion. Also provision is given in the estimate for furniture and room modernisation, fire and safety etc.

In the above circumstances, the Chief Engineer (Distribution North Malabar), Kannur requested Administrative Sanction for an amount of ₹185 lakh for the construction of Inspection Bungalow at Burnassery, Kannur.

The matter was placed before the Full Time Directors as per note read 3rd above.

Having considered the matter in detail, the Full Time Directors in the meeting held on 12/08/2020, resolved to accord revised Administrative Sanction for an amount of ₹185 lakh for the construction of Inspection Bungalow at Burnassery, Kannur in the land owned by KSEB Ltd at Burnassery, Kannur.

Orders are issued accordingly.

By Order of Full Time Directors,
Sd/-
Lekha G.
Company Secretary (In charge)

To:

The Chief Engineer (Distribution North Malabar), Kannur
The Deputy Chief Engineer, Electrical Circle, Kannur

Copy to:

The Chief Engineer (IT&CR)
The Financial Adviser/The Chief Internal Auditor
The RCAO/The RAO/The LLO
The TA to Chairman & Managing Director
The TA to Director (Distribution, IT & HRM / Transmission & System Operation /
Generation-Electrical & SCM / Generation-Civil / Planning & Safety)
The PA to Director (Finance)/ CA to Secretary (Administration)/Company Secretary
The Fair Copy Superintendent/Library/Stock File

Forwarded/By Order



Assistant Engineer