



KERALA STATE ELECTRICITY BOARD LIMITED

(Incorporated under the Companies Act, 1956)

CIN: U40100KL2011SGC027424

Registered Office: Vidyuthi Bhavanam, Pattom, Thiruvananthapuram – 695 004 Website: www.kseb.in

Phone:(O) +91 471 2514522 E-mail: dqekseb@kseb.in

Abstract

Training programme for EOT Crane operators in power stations - Sanction accorded– Orders issued.

Corporate Office (SBU-G/E)

B.O.(FTD) No. 683 /2021 (DGE/G3/General /EOT Crane/2021-22) Thiruvananthapuram dated: 18-09-2021

- Read:-
1. Letter No.CEG/AEEVI/Safety/Gnl/2021-22/239 dated:11-05-2021 of the Chief Engineer (Generation & PED),Moolamattom and the enclosed estimate.
 2. Letter No.CEG/AEE VI/Gnl/2021-22/685 dated 13-07-2021 of the Chief Engineer (Generation & PED),Moolamattom and the accompaniments
 3. Note No. DGE/G3/General /EOT Crane/2021-22 dated:16-08-2021 of the Director (GE & SCM) (Agenda item No.9/9/21)

ORDER

The Chief Engineer (Generation & PED) as per letters read 1st & 2nd above reported the shortage of trained Crane operators in most of the power stations under KSEBL. It is suggested to impart training to the selected persons employed in various power stations. Also suggested to train four to five persons from Major HEPs and one person each from SHEPs . Subsequently, budgetary offer was collected from M/s Kerala State Productivity Council (KPSC), H.M.T Road, Kalamassery for arranging training for EOT crane operators at various power stations under KSEBL and an estimate amounting to Rs.1,50,000/-has been forwarded for obtaining sanction. It is proposed to conduct training at 4 locations namely at Moolamattom, Lower Periyar ,Moozhiyar & Kakkayam PH by clubbing the stations conveniently.

With the above arrangement Overseer to Assistant Engineers/Assistant Executive Engineers in each sessions/locations, are included and around 60 employees from various power stations can be trained. It is also proposed to retain the trained employees at the respective stations as per the list attached, for five years after imparting the training.

As the estimated amount is above the delegated limits of Chief Engineer, sanction was requested for an estimate amounting to Rs.1,50,000/-(Rupees One lakh Fifty Thousand only),for arranging the subject training programme. Also requested for retaining the officers/Staff, for a minimum period of 5 years in Generation after imparting the training.

The matter was placed before the Full Time Directors as per note read as 3rd above.

Having considered the matter in detail, the Full Time Directors meeting held on 10-09-2021, resolved to accord sanction for conducting a training programme for EOT crane operators at various power stations under KSEBL, at four locations namely Moolamattom, Lower Periyar ,Moozhiyar & Kakkayam Power Stations ,at an estimated amount of Rs.1,50,000/-(One Lakh Fifty Thousand only).

Further resolved to impart training to the employees shortlisted as per Annexure and retained in Generation wing for a period of 5 years .

Orders are issued accordingly.

By Order of the Full Time Directors,

Sd/-

(LEKHA.G)

Company Secretary
(In -charge.)

To:

The Chief Engineer (Generation & PED), Moolamattom.

Copy to:

The Chief Internal Auditor/Company Secretary

The TA to CMD/D(GE)/ D(T&SO)/ D(D&IT)/D(GC)/D(PS & SCM)/D(RSS&W)

The Fair copy Superintendent/Library/Stock File

Forwarded / By Order

Asst. Executive Engineer

Annexure to B.O. (ETD) No. 683/2021 (DGE/G3 / General / EOT Cra
2021-22 dated: 18.09.2021

LIST OF EMPLOYEES WILLING TO UNDERGO EOT CRANE OPERATORS
TRAINING UNDER GENERATION WING

I. GENERATION CIRCLE MOOLAMATTOM

Idulki Power House

Sl No	Name	Designation	Employee Code	Remarks
1	Siby P.K	Line Man II	1067620	Generator Maintenance Sub Division, Moolamattom
2	Ajai Samuel	Sub Engineer (E)	1056562	Transformer Maintenance Sub Division, Moolamattom
3	Manu Thulasidasan	Sub Engineer (E)	1103691	Generation Sub Division, Moolamattom
4	Husain C.K.	Overseer (E)	1057773	Transformer Maintenance Sub Division, Moolamattom

Malankara SHEP

Sl No	Name	Designation	Employee Code	Office
1	Benny George	Overseer (E)	1046337	Maintenance Sub Division,

Note : Sri. Siby P.K., Lineman II from Generator Maintenance Sub Division, Moolamattom is proposed for training as the Sub Engineer (E) & Overseer(E) of that Sub Division are not having enough balance service as required and are retiring from service within a short period.

II. GENERATION CIRCLE KOTHAMANGALAM

Lower Periyar Power House

Sl No	Name	Designation	Employee Code	Remarks
1	Ajith N.S	Assistant Engineer (E)	1105559	Generator Section
2	Arun Dominic	Assistant Engineer (E)	1107173	Auxiliary Section
3	Rasheed M. H	Sub Engineer (E)	1057494	Auxiliary Section
4	Sreejith S.	Sub Engineer (E)	1057590	Switchyard Section

Idamalayar Power House

Sl No	Name	Designation	Employee Code	Remarks
1	Jijo Joy	Assistant Engineer (E)	1068287	SEO
2	Sreeju Krishnan	Assistant Engineer (E)	1070051	SHO
3	Varghese Paul	Sub Engineer (E)	1103806	
4	Victor T.V.	Sub Engineer (E)	1060556	
5	Abdul Rahim	Forman Grade II	1051174	

GENERATION CIRCLE THRISSURE

Poringalkuthu Power House

Sl No	Name	Designation	Employee Code	Remarks
1	Sijo K.V	Sub Engineer (E)	1057179	Generation Sub Division
2	Sudheesh P.S.	Sub Engineer (E)	1064339	Generation Sub Division
3	Manojkumar C.N.	Sub Engineer (E)	1060010	Generation Sub Division

Sholayar Power House

Sl No	Name	Designation	Employee Code	Remarks
1	Benny E.P.	Assistant Engineer (E)	1050697	Generation Sub Division
2	Anil P. Unni	Sub Engineer (E)	1057914	Generation Sub Division
3	Joby Antony	Sub Engineer (E)	1045234	Generation Sub Division

IV. GENERATION CIRCLE MEENCUT

Panniar Power House

Sl No	Name	Designation	Employee Code	Remarks
1	Vinod Antony	Sub Engineer (E)	1058178	
2	Gibi Paul	Overseer (E)	1068554	
3	Sanu A.S.	Overseer (E)	1057448	

Vellathooval SHEP

Sl No	Name	Designation	Employee Code	Remarks
1	Reny Kurian	Sub Engineer (E)	1056570	

Neriamangalam Power House

Sl No	Name	Designation	Employee Code	Remarks
1	Kannan P.	Overseer (E)	1043716	

Pallivassal Power House

Sl No	Name	Designation	Employee Code	Remarks
1	Ashraf P.S.	Sub Engineer (E)	1055022	
2	Sudheeshkumar R.	Overseer (E)	1054154	
3	Moorthiswamy	Overseer (E)	1048895	
4	K.V.George	Overseer (E)	1039861	

Perunthenaruvi SHEP

SI No	Name	Designation	Employee Code	Remarks
1	Pradeep K.B	Assistant Engineer (E)	1049860	

Ranni-Perunad SHEP

SI No	Name	Designation	Employee Code	Remarks
1	Renjith T.V.	Sub Engineer (E)	1067572	

Kallada SHEP

SI No	Name	Designation	Employee Code	Remarks
1	Anish S.A	Sub Engineer (E)	1103673	

Peppara SHEP

SI No	Name	Designation	Employee Code	Remarks
1	Vishnu V.S.	Sub Engineer (E)	1103499	Maintenance

Lower Meenmutty SHEP

SI No	Name	Designation	Employee Code	Remarks
1	Syamkumar S.	Sub Engineer (E)	1057007	Maintenance

VI. GENERATION CIRCLE KOZHIIKKODE

Kakkayam Power House

SI No	Name	Designation	Employee Code	Remarks
1	Nizar K.M	Assistant Engineer(E)	1104442	RMU Sub Division
2	Mohandas K.P.	Sub Engineer (E)	1066454	MMSD
3	Prajeesh K	Sub Engineer (E)	1066966	EMSD
4	Sreekanth K.S.	Sub Engineer (E)	1070124	MMSD
5	Johnson Philip	Overseer	1051645	O&C

Kuttiyadi Tail Race

SI No	Name	Designation	Employee Code	Remarks
1	Prajeesh M.	Sub Engineer (E)	1055300	

Maduppetty SHEP

Sl No	Name	Designation	Employee Code	Remarks
1	Shanmukhadas G.	Sub Engineer (E)	1059465	

Sengulam Power House

Sl No	Name	Designation	Employee Code	Remarks
1	Sajan T.R.	Sub Engineer (E)	1055020	
2	Saji A.S.	Overseer (E)	1036367	

Scada Sub Division Vellathooval

Sl No	Name	Designation	Employee Code	Remarks
1	Asok kumar P.G.	Sub Engineer (E)	1058314	

V. GENERATION CIRCLE MOOZHİYAR

Sabarigiri Power House

Sl No	Name	Designation	Employee Code	Remarks
1	Anish Chandran	Lineman II	1068886	Mech Maint Sub Dvn
2	Sherif C.H	Lineman II	1068894	Mech Maint Sub Dvn
3	Binu M.R	Lineman II	1068887	Mech Maint Sub Dvn
4	Santhosh T.A.	Lineman II	1063444	Elect Maint Sub Dvn
5	Sanjayan V.	Lineman I	1060588	Elect Maint Sub Dvn

Note : The Deputy Chief Engineer, Generation Circle, Moozhiyar reports that only the above mentioned Lineman are willing to undergo the EOT crane Operators training.

Kakkad Power House

Sl No	Name	Designation	Employee Code	Remarks
1	Sukesh S.S.	Assistant Engineer (E)	1065309	
2	Arunjith M.	Assistant Engineer (E)	1107213	
3	Abdul Rasheed E.M.	Sub Engineer (E)	1056933	
4	Pradeep P.	Sub Engineer (E)	1058545	
5	Rajendran Nair K.P	Overseer	1050727	

Chembukadavu SHEP

SI No	Name	Designation	Employee Code	Remarks
1	Jereesh T.A.	Sub Engineer (E)	1103446	

Urumi SHEP

SI No	Name	Designation	Employee Code	Remarks
1	Sasidharan V.	Sub Engineer (E)	1055175	

Poozhithode SHEP

SI No	Name	Designation	Employee Code	Remarks
1	Lalu V.P.	Sub Engineer (E)	1056489	

Vilangad SHEP

SI No	Name	Designation	Employee Code	Remarks
1	Shiju K.	Sub Engineer (E)	1058450	

Sd/-
DIRECTOR (G-E)